

## Construction Progress Update through 1/28/2015

- Elevator Bank complete.
- Second level of Stair A pored, forming final level.
- Steel erection has begun.
- Backfill complete on foundation wall.
- Waterproofing complete until spring. .



Elevator core walls complete.



Third and final level of Stair A being formed.





Steel Erection has begun.





West wall water proofed and backfilled.





South wall water proofed and back filled.



South dirt stockpile removed.