

## Progress Pictures Through 11/05/15



Landscaping and Railing on South side of Clinic.

## Progress Pictures Through 11/05/15



Interior Wood Paneling on Second floor.

## Progress Pictures Through 11/05/15



Entry Snowmelt apron poured.

## Progress Pictures Through 11/05/15



Fencing and Landscaping along North West Retaining wall.

## Progress Pictures Through 11/05/15



Wall mounted items and blinds installed second level.

## Progress Pictures Through 11/05/15



Carpeting being installed first level.

## Progress Pictures Through 11/05/15



Millwork installed first level.

## Progress Pictures Through 11/05/15



Decorative wall Paneling installed.