## ConstructionProgress Update through 12/10/2014

- Interior pad footings are 85% complete.
- Foundation footings and Grade beams now 85% complete.
- Poured first level of double elevator core wall.
- Forming Stair B first level core wall.
- Crane has been delivered that will assist in forming and pouring upper levels of core walls.



Foundation grade beams poured on the north side of building.



Stair B core walls being formed.



Rebar tied for first level of Stair B location with door openngs.