

## Construction Progress Update through 12/31/2014

- Interior pad footings are 90% complete.
- Foundation footings and Grade beams now 100% complete.
- Poured 2<sup>nd</sup> level of double elevator core wall.
- Poured 3<sup>rd</sup> level of Stair B core walls.
- Forming 4<sup>th</sup> level of Stair B core walls.
- Forms delivered and being prepped for Stair A core walls.



Foundation footings and grade beams completed .



2<sup>nd</sup> level of the elevator core walls poured.



Stair B 3<sup>rd</sup> level poured and beginning to form 4<sup>th</sup> and final level.



Forms delivered and being prepped for Stair A core walls.