- Steel Erection working on final detailing
- Underground plumbing complete
- Plumbers working on rain leaders and core drilling
- Fireproofing being applied on 1st floor then moving to 3rd floor
- 3hr seperation wall complete
- Electricians running conduits on 2nd floor
- Framers finishing walls 2nd lvl and finishing exterior walls
- Summit sprinklers working on branch lines 2nd level
- Slab on grade complete



West Elevation




North East Elevation



North West Elevation




South Elevation




Framing and Ductwork progress 2nd level



3 Hr Seperation wall in place



Exterior wall framing 3rd level



Exterior wall framing 3rd level



1st floor slab on grade